RIG IT RIGHT!

Proper Landing Gear Rigging Procedures

for

Cessna 300 and 400 Series Twins

with

Electro-mechanical Landing Gear

Compiled by:

The Twin Cessna Flyersm P.O Box 12453 Charlotte, NC 28220

www.twincessna.org

Follow all of the steps in the order that they appear. For all specifications, the latest, up to date, service manual for the model in question must be used.

Key to Symbols



= Visually Inspect



= Disconnect



= Reconnect



= Physically Check



= Adjust



= OK to Proceed



= Not OK to Proceed

The Twin Cessna Flyer P.O. Box 310 New Haven, IN 46774 (260) 749-2520 www.twincessna.org Thank you for your interest in the proper landing gear rigging procedures for the Cessna 300 and 400 Series twins. The following procedure is recommended for all models equipped with electro-mechanical landing gear.

The National Transportation Safety Board has nearly 800 accidents on file involving the landing gear on only the 310 through 310R models alone. In almost half of these accidents, the aircraft was landed without the landing gear down and locked. If the landing gear accidents and incidents were eliminated, the Cessna 310 would be the safest airplane in the sky. We have found that all Cessna twins with electro-mechanical landing gear should have the gear completely inspected and re-rigged every 200 hours or annually, whichever comes first.

The following pages, along with the DVD, should be used as a guide and must be used **only** with the **latest up-to-date Service Manual** for the aircraft model involved. Rig It Right is not intended to replace the Service Manual and should be used only as an additional guide to rigging procedures.

Getting Started

The following is a list of items necessary for proper gear rigging:

- 1. Basic hand tools including a flashlight.
- 2. A spring scale that reads from 0 to 150 pounds.
- 3. Cessna part number 080001-1, a tool for rigging main gear door tensions.
- 4. The current Service Manual for the particular airplane involved.
- 5. An auxiliary power unit is advisable to eliminate excessive power drain on the aircraft batteries.
- 6. The aircraft must be placed on jacks using the Service Manual as a guide.

Remember, the proper up-to-date Service Manual must be used for the correct specifications. All steps must be followed in the order printed and no steps should be left out. We have found the following procedure will work well on all models with electromechanical landing gear.

The Twin Cessna Flyer and Larjan Publications assumes no liability for damages to equipment or personal injury incurred as a result of improper use of the following procedures.

DISCONNECTING: Landing Gear Doors

PROCEDURE STEP RESULT NOSE GEAR DOOR ' Y A MAIN GEAR DOOR MAIN GEAR NOSE GEAR RAISE LANDING REMOVE ATTACHING **GEAR 20 TO 30** SECURE DOORS NUT FROM ACTUATOR DEGREES OUT OF THE WAY RUN LANDING GEAR DOWN NOTE DISCONNECT NOSE SUPPORT IN-GEAR FORK BOLT DISCONNECT FROM TORQUE BOARD DRIVE INBOARD MAIN

TUBE

TUBE DURING

GEAR BOX


OPERATION


CHECKING: Up and Down Limit Switches

AND INTERMEDIATE


DRIVE TUBE

DRIVE TUBE







CHECKING: Drive Tubes, Trunnions, Retracting Linkage, and Wheel Well area




CHECKING: Main Gear Door Actuator Arm Tension Gear Down




CHECKING: Main Door Actuator Arm Tension Gear Up




ADJUSTING: Main Door Arm Actuator Tension Gear Up and Gear Down




CHECKING: Main Landing Gear Free Fall




ADJUSTING: Main Landing Gear Free Fall



CHECKING: Landing Gear Drop Off * SEE NOTES







Notes

* WHILE CHECKING PROPER DROP OFF AS SHOWN IN STEP 17, PUT A SMALL WAD (MARBLE SIZE) OF MODELING CLAY, PLAY DOUGH OR WINSHIELD STRIP CAULK ON THE HUB CAP OF THE WHEEL. THIS WILL INDICATE HOW HIGH THE GEAR TRAVELS IN THE WELL. THE LANDING GEAR HUB WHEN UP AND LOCKED SHOULD NOT TOUCH THE AIRFRAME, 1/8 TO 1/4 INCH CLEARANCE IS DESIRABLE.


CHECKING: Down Lock Tension




ADJUSTING: Down Lock Tension




CHECKING: Uplock Hooks For Engagement




ADJUSTING: Uplock Hooks For Engagement




CHECKING: NOSE GEAR IDLER BELLCRANK FOR LOOSENESS




CHECKING: Nose Gear Connector Link For Overcenter Travel




ADJUSTING: Nose Gear Connector Link For Overcenter Travel




CHECKING: NOSE GEAR RETRACTION




ADJUSTING: NOSE GEAR RETRACTION




CHECKING: Nose Gear Down Lock Tension




ADJUSTING: Nose Gear Downlock Tension




CHECKING: Nose Gear Uplock Tension




ADJUSTING: Nose Gear Uplock Tension




CHECKING: Nose Gear Uplock Engagement




CHECKING: Gear Down Indicator Light Switches For Proper Adjustment




ADJUSTING: Nose Gear Down Indicator Light Switch




ADJUSTING: Main Landing Gear Indicator Light Switch



CHECKING: Nose and Main Landing Gear Doors For Proper Fit



CHECKING: Safety Switch Inspection



5		
		4



TAKE YOUR CESSNA HOME FOR SERVICE AT THE SIGN OF THE CESSNA SHIELD"

multi-engine SERVICE LETTER

MARKETING DIVISION . CESSNA AIRCRAFT COMPANY WICHITA, KANSAS 67201 . CABLE ADDRESS / CESSCO WICHITA

January 5, 1976

ME76-2

SUBJECT: WING RIB IMPROVEMENT -- MAIN LANDING GEAR SIDE BRACE

AIRCRAFT APPLICABILITY: All 300/400 Series Aircraft (except Skymaster)

with the following serials ...

310	35000 and on	402 402-0001 thru 402B1003
320	320-0001 thru 320F0045	411 411-0001 thru 411A0300
	340-0001 thru 340A0002	414 414-0001 thru 414-0802
	401-0001 thru 401B0221	421 421-0001 thru 421B0970

REASON FOR LETTER:

Reinforcement plates and angles have recently been added to the wing ribs in the main landing gear wheel well area on the model 340 & 400 series production aircraft.

These improvements in strength and service life of the main landing gear mounting structure were specifically designed for aircraft engaged in heavy usage such as air taxi, rough field operation, etc.

ACTION REQUIRED:

It is recommended that the following items be checked as part of all landing gear inspections, especially on high time, heavy usage aircraft.

- Inspect main gear upper side brace support for looseness and the support attach bolts for proper torque (reference applicable Service Manuals for torque values).
- 2. Inspect wheel well ribs for cracks in accordance with the attached instructions.

At any time cracks are found on in-service aircraft, the wing rib is to be repaired by installing Service Kit SK414-8E which incorporates the same structural improvements mentioned above.

PARTS INFORMATION:

Service Kit SK414-8E may be purchased through the Cessna Dealer Organization at a suggested list price of \$89.40 (S) each.

Page 2 of ME76-2 dated dated January 5, 1976


REMARKS:

- Service Kit SK414-8E is applicable to the Model 310 and all earlier 300/400 series aircraft and should be installed on an "as required" basis.
- 2. This Service Letter supersedes ME71-2 dated February 12, 1971.
- 3. Owners and operators of applicable aircraft should contact their Cessna , Dealers for further details concerning this Service Letter.

(Owner Notification System - No. 1)

ALL PRICES SUBJECT TO CHANGE WITHOUT NOTICE

CESSNA AIRCRAFT COMPANY



VIEW LOOKING GUTEGARD AT RH MAIN GEAR WHEEL WELL INBOARD WING RIB (LH OPPOSITE)

INSPECTION:

- 1. Inspect wing ribs in LH and RH main landing gear wheel wells, at main landing gear side brace supports (forgings) upper and lower attach points for cracks and insure support attach bolts are tight, torqued in accordance with your aircraft service manual torque values.
- Cracks are sometimes found in the existing doubler on inboard side of wing rib, at
 the top of the cut out in rib web for the aft push-pull tube (torque tube to landing
 gear bellcrank) and near the landing gear side brace support, upper and lower attach
 bolts.
- 3. If cracks are existing in the wing rib, repair rib by installing Service Kit SK414-8, Wing Rib Modification Main Landing Gear Side Brace.